

Inspection Photos 09/28/18
Location: KP Kauffman Amoco-Charter-Schneider Facility
Location ID #405998



K.P. Kauffman signage at tank battery.



Hydro – excavation work being completed to expose flowlines in the area of release (view North)

Inspection Photos 09/28/18
Location: KP Kauffman Amoco-Charter-Schneider Facility
Location ID #405998



Excavation work exposed numerous flowlines in the area of release south of the flowline manifold (pictured at top).



An external corrosion hole was found on the 3" un-coated carbon steel flowline associated with the Amoco-Charter-Schneider 12A well (API 123-09038); a section of this flowline was removed.

Inspection Photos 09/28/18
Location: KP Kauffman Amoco-Charter-Schneider Facility
Location ID #405998



Approximately 20' of 3" flowline was cut out and removed from the excavation (shown on left side of photo)



Close up view of a corrosion hole found on the failed section of flowline associated with the Amoco-Charter-Schneider 12A well (API 123-09038)

Inspection Photos 09/28/18
Location: KP Kauffman Amoco-Charter-Schneider Facility
Location ID #405998



Repairs/ replacement section of flowline (2" HDPE) being installed/ connected to the existing flowline pipe on the south end of the excavation.



Replacement section of flowline connected to the flowline manifold on the north end of the excavation.