

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2018

Submitted Date:

10/05/2018

Document Number:

691401135**FIELD INSPECTION FORM**

Loc ID 320135 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10602Name of Operator: MCCLANE ENERGY INCAddress: 1412 103 RD AVECity: NORTHGLENN State: CO Zip: 80260**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
MCCLANE, GENE		genemcclane@hotmail.com	All inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202786	WELL	PR	08/01/2016	OW	001-08191	VAN SCOYK 1	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	NFPA Label on produced water tank has a flammability number of 0, 10/20/2016 FIR (doc #678800128) indicates that this label should have a minimum flammability of 1.		
Corrective Action:	Immediately correct placards to comply with Rule 210.d.	Date:	11/22/2016
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Numerous items of unused equipment all around pumpjack. See location photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	11/05/2018
Type			
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stained soil near jumpjack motor and wellhead.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.e	Date:	11/05/2018
Type	TRASH		
Comment:	Several oil jugs and buckets around pumpjack. See locaiton photos. E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907.		
Corrective Action:	Comply with Rule 603.f .	Date:	10/19/2018

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:				corrective date
Type: Emission Control Device	# 1			

Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	202786	Type:	WELL	API Number:	001-08191	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:								Date:	
BradenHead									
Comment:		Plumbed to surface							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Any corrective actions from previous inspections that have not been address are still applicable.	beardslt	10/05/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691401136	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4600300