

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2018

Submitted Date:

10/05/2018

Document Number:

691200585

**FIELD INSPECTION FORM**

Loc ID 323041 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Findings:**

13 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244678	WELL	SI	09/01/2017	OW	123-12473	PERSON 2-2	TA

**General Comment:**

[This is a WELL & BATTERY inspection.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:	Smooth strand wire.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	Valves shut & inlet LOTO.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	DCP. Valves shut & LOTO.		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Controls crude oil tank VOCs.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		

Comment:	
Corrective Action:	Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment: <a href="#">This Centralized Battery serves 3 locations (323041, 305639, 305638).</a>					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	48 Bbls.				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: <a href="#">Shares berms with crude oil tank.</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.427992,-104.518753
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berms w/ produced H2O vault.				
Corrective Action:				Date:

<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 244678 Type: WELL API Number: 123-12473 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA. Wellhead master valves are shut, LOTO, & disconnected from flowline. Well is incapable of being produced in current status. Plunger lift equipment on site has been removed from well. Records indicate SI since 06/2015. SI for RISE. Well is on exemption list, see DOC#401474555.

Corrective Action:

Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead appears plumbed to surface.

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Observed a rathole on the north side of wellhead that is approximately 1.5 feet in diameter and approximately 2 feet deep. This could potentially constitute a safety hazard. See attached photo.	evinsb	10/05/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200587	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4600383">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4600383</a>