

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2018

Submitted Date:

10/04/2018

Document Number:

693700037**FIELD INSPECTION FORM**
 Loc ID 318027 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Allison, Rick		rick.allison@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
119690	PIT	AC			-	NEW WINDSOR UNIT	EI
240451	WELL	SI	04/01/2018	OW	123-08239	CANAL 2	EI

General Comment:

Inspected Facilities									
Facility ID:	119690	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	240451	Type:	WELL	API Number:	123-08239	Status:	SI	Insp. Status:	EI

Environmental**Spill/Remediation:**

Comment: COGCC onsite meeting with Operator, consultant, and surface owner to discuss ongoing remediation at former tank battery and former pit. Additional excavation will occur in vicinity of dumpline release at former tank battery to address remaining hydrocarbon impacts in base and north wall of excavation. Operator will conduct additional soil and a groundwater assessment at former produced water pit.

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____

Wildlife Protection Devices (fired vessels): _____