

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2018

Submitted Date:

10/05/2018

Document Number:

689302076

FIELD INSPECTION FORM

Loc ID 334803 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 18 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211583	WELL	PR	08/02/2001	GW	045-07344	BERNKLAU RMV #114-33	PR
289629	WELL	PR	05/25/2008	GW	045-13837	HILLTOP 2F2 RANCH LLC RWF 423-33	PR
289630	WELL	PR	11/28/2007	GW	045-13836	HILLTOP 2F2 RANCH LLC RWF 23-33	PR
289631	WELL	PR	03/31/2008	GW	045-13835	HILLTOP 2F2 RANCH LLC RWF 24-33	PR
289632	WELL	PR	03/07/2007	GW	045-13834	HILLTOP 2F2 RANCH LLC RWF 434-33	PR
289635	WELL	PR	03/07/2007	GW	045-13831	HILLTOP 2F2 RANCH LLC RWF 321-4	PR
289636	WELL	PR	03/07/2007	GW	045-13830	HILLTOP 2F2 RANCH LLC RMV 109-4	PR

General Comment:

[Routine Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Emergency Contact Number:			
Comment:	1-970-285-9377		
Corrective Action:			Date:

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	unused equipment, see photos		
Corrective Action:	Comply with Rule 603.f .		Date: 01/05/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Hog panel fence		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panel fence		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panel fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	not in use, see photo		
Corrective Action:			Date:
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:			Date:

Type: Deadman # & Marked	# 9	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 6	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Hole in secondary containment liner, see photo			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 11/05/2018

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	211583	Type:	WELL	API Number:	045-07344	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	289629	Type:	WELL	API Number:	045-13837	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	289630	Type:	WELL	API Number:	045-13836	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	289631	Type:	WELL	API Number:	045-13835	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	289632	Type:	WELL	API Number:	045-13834	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	289635	Type:	WELL	API Number:	045-13831	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	289636	Type:	WELL	API Number:	045-13830	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Seeding						
Culverts						
Berms						
		Compaction				

Comment: [unstabalized slope behind separators, sediment being moved onto location.see photos](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 11/05/2018

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302077	Inspection photo 689302077	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4601639