

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2018

Submitted Date:

10/05/2018

Document Number:

689500868**FIELD INSPECTION FORM**
 Loc ID 323216 Inspector Name: Oakman, Kari On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name            | Phone | Email                                  | Comment                         |
|-------------------------|-------|--|---------------------------------|
| ,                       |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM | <a href="#">All Inspections</a> |
| Graber, Candice (Nikki) |       | candice.graber@state.co.us             |                                 |
| Axelson, John           |       | john.axelson@state.co.us               |                                 |

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.  
Photos attached to document site condition at the time of inspection.

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: COGCC field follow up to REM 5350. Last monitoring report submitted 11/26/2016. MW2, MW9-MW15 are on site and appear in good condition, MW5-MW8 were off location and not inspected. AS/SVE wells still in place.

Corrective Action: Submit monitoring reports for 2017 and Q1-Q3 2018. Additional well(s) may be required to achieve point of compliance.

Date: 11/05/2018

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_

Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 689500869    | 10/5/2018 Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4601659">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4601659</a> |