

Inspection Photos

Location Name: Spill/Release Point ID #451553
REM #10395



Gathering line ROW south of project area.



View of ROW from near Spill/Release Point ID #451553.



Inspection Photos
Location Name: Spill/Release Point ID #451553
REM #10395



Spill/Release Point ID #451553.



View of revegetation in progress within project area.

Inspection Photos
Location Name: Spill/Release Point ID #451553
REM #10395



View along southern edge of perimeter fencing, facing east.



View along northern edge of perimeter fencing, facing east.

Inspection Photos

Location Name: Spill/Release Point ID #451553

REM #10395



Revegetation along slope east of release point.



Eastern extent of perimeter fencing. Evidence of significant livestock traffic noted across the region.



Inspection Photos
Location Name: Spill/Release Point ID #451553
REM #10395



View of interior of project area from the eastern edge facing west.



Both 2" valves are locked out in the closed position.