

**Inspection Photos**  
**Location Name: Diemoz A pad**  
**Location: 419380**



**Stack on North side of pad 35ft from stock panel**



**Stack is 35 ft from the stock panel around well head**



**Inspection Photos**  
**Location Name: Diemoz A pad**  
**Location: 419380**



**Equipment stored on the west side of location**



**Equipment stored at the SW corner of location**

Inspection Photos  
Location Name: Diemoz A pad  
Location: 419380



Well head sign does not include all required information



Stack at the SE corner of location is 55ft from stack panel



**Inspection Photos**  
**Location Name: Diemoz A pad**  
**Location: 419380**



**Entry of location**



**Pad looking SW**



**Inspection Photos**  
**Location Name: Diemoz A pad**  
**Location: 419380**



**Drain path cut into pad to move storm water away from hay**



**Drain path on east side of pad**



**Inspection Photos**  
**Location Name: Diemoz A pad**  
**Location: 419380**



**Drain path moving off of pad, no stabilization or BMP's**



**Storm water routed off of location into existing ditch**



**Inspection Photos**  
**Location Name: Diemoz A pad**  
**Location: 419380**



**Notified operator of Storm Water Impacts on 10/9,  
requesting immediate action.**



**10/10 no action taken by operator to install BMP.**