

# Inspection Photos

Operator: Hilcorp Energy Co.

API: 05-067-07031

Date: 10/03/2018



**Photo 1. View of the project area from the northern corner facing center.**





**Photo 2. View of the eastern project area from the northern corner facing southeastward. Vegetation is becoming established with grasses such as western wheatgrass (*Pascopyrum smithii*) , sand dropseed (*Sporobolus cryptandrus*), and forbs such as hairy goldenaster (*Heterotheca villosa*).**





**Photo 2. View of the western project area from the southern corner facing northward.**





**Photo 3. View of area in the southern project area where stormwater flows off of the well pad, scouring the rocky upper portions, and depositing sediment down-slope.**





**Photo 4. View of another area where erosional scouring and erosional channels are forming within the western project area.**