

Inspection Photo
Mamm Creek Fed. 13D
API # 045-12492
Inspection # 689302107



Location Photo #1

Location Photo #2

Inspection Photo
Mamm Creek Fed. 13D
API # 045-12492
Inspection # 689302107



Location Photo #3, missing sign



Location Photo #4, missing sign

Inspection Photo
Mamm Creek Fed. 13D
API # 045-12492
Inspection # 689302107



Location Photo #5, Leaking casing valve



Location Photo #6, Non-legible label

Inspection Photo
Mamm Creek Fed. 13D
API # 045-12492
Inspection # 689302107



**Location Photo #7, unused/unmarked
flowline riser**



**Location Photo #8, Storm water issue,
sediment being moved off location.**

Inspection Photo
Mamm Creek Fed. 13D
API # 045-12492
Inspection # 689302107



**Location Photo #9, storm water issue,
Sediment being moved from location**

