

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/11/2018

Submitted Date:

10/11/2018

Document Number:

689302105**FIELD INSPECTION FORM**
 Loc ID 334859 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerusoilandgas.com	all Piceance inspections
Murray, Richard		g.richard.murray@state.co.us	Pipeline group

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211532	WELL	PR	07/15/1998	GW	045-07292	BOULTON 33-6	PR
261014	WELL	PR	01/16/2003	GW	045-07925	SHIDELER 33-3A (F33)	PR
261015	WELL	PR	01/07/2003	GW	045-07926	SHIDELER 33-3 (F33)	PR
261016	WELL	PR	01/12/2003	GW	045-07927	BOULTON 33-6A (F33)	PR
263373	WELL	PR	01/21/2003	GW	045-08127	SHIDELER 33-4C2 (F33)	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date:

Good Housekeeping:

Type	OTHER		
Comment:	Stained rock in battery containment		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e..	Date:	11/11/2018
Type	UNUSED EQUIPMENT		
Comment:	unused equipment (kimray bonnets) next to separators Unused flowlines behind separators and in tank battery containment		
Corrective Action:	Comply with Rule 603.f . For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	11/11/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:	7 of 8 marked. 1 between tank battery and East wellhead not marked, see photo		

Corrective Action: Mark as required	Date: 10/26/2018
--	-------------------------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment: Centralized battery						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)	Methanol tank	
Other (Capacity)	1000 gallon	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211532	Type:	WELL	API Number:	045-07292	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	261014	Type:	WELL	API Number:	045-07925	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	261015	Type:	WELL	API Number:	045-07926	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	261016	Type:	WELL	API Number:	045-07927	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	263373	Type:	WELL	API Number:	045-08127	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Slope Roughening						
Seeding						
Berms						
		Gravel				
Ditches						

Comment: Storm water issue next to NorthEast side of separators, water leaching from rock in to ditch around location. see photo
 SW side of location storm water moving sediment off location. see photo

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 10/26/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302106	Inspection photo 689302106	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4605972