

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2018

Submitted Date:

10/15/2018

Document Number:

689302114**FIELD INSPECTION FORM**

Loc ID 335511 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300395	WELL	PR	06/01/2011	GW	045-17901	DOWNING RWF 522-24	PR
300396	WELL	PR	06/30/2010	GW	045-17902	DOWNING RWF 22-24	PR
300397	WELL	PR	06/30/2010	GW	045-17903	DOWNING RWF 511-24	PR
300398	WELL	PR	06/30/2010	GW	045-17904	DOWNING RWF 311-24	PR

General Comment:[Routine Field Inspection](#)

Location					
Lease Road:					
Type	Access				
comment:	Rutted acces road, requires 4x4 to access and egress location				
Corrective Action	Repair and maintain lease road.				Date: 11/15/2018
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:	1-970-285-9377				
Corrective Action:					Date:
Good Housekeeping:					
Type	UNUSED EQUIPMENT				
Comment:	Unused equipment, see photo				
Corrective Action:	Comply with rule 603.f.				Date: 01/15/2019
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	TANK BATTERY				
Comment:	Hog panel fence				
Corrective Action:					Date:
Type	SEPARATOR				
Comment:	Hog panel fence				
Corrective Action:					Date:
Type	WELLHEAD				
Comment:	Hog panel fence				
Corrective Action:					Date:
Equipment:					
					corrective date
Type: Pig Station	# 1				
Comment:					
Corrective Action:					Date:
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:					Date:

Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 4	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Chemical unit at wellheads	
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:	Not in use	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

Inspected Facilities									
Facility ID:	300395	Type:	WELL	API Number:	045-17901	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	300396	Type:	WELL	API Number:	045-17902	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	300397	Type:	WELL	API Number:	045-17903	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	300398	Type:	WELL	API Number:	045-17904	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				no gravel, only dirt
		Compaction				rutted road
Seeding						
Berms						
Ditches						

Comment: [Lease entrance road rutted and needs 4x4 to access pad when wet](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302115	Inspection photo 689302115	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4608382