

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2018

Submitted Date:

10/15/2018

Document Number:

689302116**FIELD INSPECTION FORM**

Loc ID 323818 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10550Name of Operator: MUSTANG RESOURCES LLCAddress: 1660 LINCOLN STREET SUITE 1450City: DENVER State: CO Zip: 80264**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Coutts, Brandon		bcoutts@mustangresourcesllc.com	
Lemon, Deb		dlemon@mustangresourcesllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210875	WELL	PR	12/01/2016	GW	045-06633	DOWNING 24-22-6S-94W	PR

**General Comment:**

Routine Field inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Rutted access road, requires 4x4 to access and egress when muddy.		
Corrective Action	Repair and maintain lease road.	Date:	11/15/2018

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign information inaccurate at well. see photo		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	11/15/2018

Emergency Contact Number:

Comment: 1-888-291-8588

Corrective Action:

Date:

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Uncontrolled weeds on location. see photo		
Corrective Action:	Comply with Rule 603.f .	Date:	10/26/2018

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

<b>Inspected Facilities</b>				
Facility ID: 210875	Type: WELL	API Number: 045-06633	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302117	Inspection photo 689302117	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4608383">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4608383</a>