

## Inspection Photos

Location Name: Watson Ranch B Pad

Location ID: #440705

Inspection Date: October 1, 2018



Photo #1 – Location sign.



Photo #2 – View of wellheads from NE corner.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Watson Ranch B Pad

Location ID: #440705

Inspection Date: October 1, 2018



**Photo #3 – Cuttings stockpile located at SW corner of pad.**



**Photo #4 – Evidence of stormwater runoff and sediment transport at SE corner of cuttings stockpile.**



## Inspection Photos

Location Name: Watson Ranch B Pad

Location ID: #440705

Inspection Date: October 1, 2018



**Photo #5 – Vegetation growth and lack of stormwater control at SW cuttings stockpile.**



**Photo #6 – Unused equipment storage on SW cuttings stockpile.**

## Inspection Photos

Location Name: Watson Ranch B Pad

Location ID: #440705

Inspection Date: October 1, 2018



**Photo #7 – View of SE cuttings stockpile from west.**



**Photo #8 – Vegetation growth and lack of stormwater control at SE cuttings stockpile.**



## Inspection Photos

Location Name: Watson Ranch B Pad

Location ID: #440705

Inspection Date: October 1, 2018



**Photo #9 – View along south side of SE cuttings stockpile. Note lack of stormwater control and presence of tire tracks along stockpile.**



**Photo #10 – Special Waste stockpile located east of SE cuttings stockpile. Hydrocarbon odor detected from stockpiled material on inspection date. Note that this stockpile has earthen berm on three sides.**



## Inspection Photos

Location Name: Watson Ranch B Pad

Location ID: #440705

Inspection Date: October 1, 2018



**Photo #11 – View of SE Special Waste stockpile from east side. Note absence of earthen berm and presence of equipment tracks on this side of stockpile.**



**Photo #12 – Special Waste stockpile sign located in NE corner of pad outside of metal container. Note localized accumulations of oil-stained soil on ramp leading into container (red arrows).**



**Inspection Photos**  
**Location Name: Watson Ranch B Pad**  
**Location ID: #440705**  
**Inspection Date: October 1, 2018**



**Photo #13 – View of NE Special Waste stockpile from north side. Hydrocarbon odor detected from stockpiled material on inspection date. Note stockpiled material accumulation outside of metal container (red arrow). Operator was instructed to remove this impacted material during inspection.**



**Photo #14 – Additional Special Waste stockpile located in NE corner of pad did not appear to contain hydrocarbon-impacted material. Note presence of soil, boulders, road base, sawdust, wooden debris, black plastic, and vegetation. Pile also lacks stormwater control.**



**Inspection Photos**  
**Location Name: Watson Ranch B Pad**  
**Location ID: #440705**  
**Inspection Date: October 1, 2018**



**Photo #15 – Cuttings were also present in NE Special Waste stockpile (red arrow).**



**Photo #16 – View of NE Special Waste stockpile from the east. Note white materials storage containers within stockpile (red arrow) and absence of stormwater control on this side of stockpile.**



## Inspection Photos

Location Name: Watson Ranch B Pad

Location ID: #440705

Inspection Date: October 1, 2018



**Photo #17 – Overview of NE Special Waste Stockpiles from NE corner of pad. Note lack of stormwater control and presence of stained soil outside of metal container (red arrow).**



**Photo #18 – Localized accumulations of oil-stained soil on pad surface.**

**Inspection Photos**  
**Location Name: Watson Ranch B Pad**  
**Location ID: #440705**  
**Inspection Date: October 1, 2018**



**Photo #19 – Localized accumulations of stained soil on pad surface.**



**Photo #20 – Localized accumulations of stained soil on pad surface.**