

Inspection Photos

Operator: Hilcorp Energy Co.

API: 05-067-07550

Date: 10/03/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Vegetation is becoming established with grasses such as western wheatgrass (*Pascopyrum smithii*), sand dropseed (*Sporobolus cryptandrus*), and forbs such as hairy goldenaster (*Heterotheca villosa*).





Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of area in the eastern cut-slope where rilling is occurring on sparsely vegetated slope.