

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/15/2018

Submitted Date:

10/15/2018

Document Number:

689302122

FIELD INSPECTION FORM

Loc ID 335376 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	Pipeline group
Elsener,		COGCC.inspections@caerusoilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261293	WELL	PR	07/17/2002	GW	045-07941	GMR 27-2B1 (B27)	PR
261294	WELL	PR	05/13/2014	GW	045-07942	GMR 27-3D1 (B27)	PR
261296	WELL	PR	09/18/2002	GW	045-07944	GMR 27-7B1 (B27)	PR
263861	WELL	PR	10/27/2002	GW	045-08148	GMR 22-15D (B27)	PR

General Comment:

[Routine Field Inspection](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Emergency Contact Number:			
Comment:	1-800-791-7691		
Corrective Action:		Date:	
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused flow line risers		
Corrective Action:	Comply with rule 603.f. For unused, unmarked flowline risers, 24 hrs to LOTO, 30 days to remove riser		Date: 11/15/2018
Type	OTHER		
Comment:	Stained material in battery containment.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e..		Date: 11/15/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	
Equipment:			
Type: Horizontal Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:	4 of 5 marked, 1 anchor on East end of location not marked		
Corrective Action:	Mark as required	Date:	10/30/2018
Type: Other	# 1		
Comment:	Blow down vessel on East end of location.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			

Corrective Action:		Date:	
Type: Pig Station	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	Methanol tank
Other (Capacity)	1000 gallon
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 261293 Type: WELL API Number: 045-07941 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 261294 Type: WELL API Number: 045-07942 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 261296 Type: WELL API Number: 045-07944 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 263861 Type: WELL API Number: 045-08148 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Gravel				
		Compaction				
Ditches						
Seeding						
Slope Roughening						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302123	Inspection photo 689302123	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4609762