

# Inspection Photos

Operator: BP America

API: 05-067-08323

Date: 10/03/2018



**Photo 1. View of the project area from the southeastern corner facing center.**





Photo 2. View of the eastern project area from the southeastern corner facing northward. Vegetation is becoming established with grasses such as western wheatgrass (*Pascopyrum smithii*) and intermediate wheatgrass (*Thinopyron intermedium*).





**Photo 3. View of the northern project area from the northeastern corner facing westward.**





**Photo 4. View of area in the western cut-slope where straw blanket was recently installed for erosion control.**





10/03/2018

**Photo 5. Closeup view of disturbed soil in the western project area with visible seed on soil surface.**





**Photo 6. View of weeds in eastern project area that appear to be treated.**