

Inspection Photos

Operator: BP America

API: 05-067-07158

Date: 10/03/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Vegetation is becoming established with grasses such as western wheatgrass (*Pascopyrum smithii*), smooth brome (*Bromus inermis*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the northern project area from the northeastern corner facing westward. Stormwater diversion is recently graded.



Photo 4. View of the southwestern project area from the southwestern corner facing northward. Berm and lower project area was recently graded and seeded.



Photo 5. View of cobble run-down and silt trap within the eastern project area.



Photo 6. Closeup view of seed apparent on disturbed soil surface.