

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/11/2018

Submitted Date:

10/11/2018

Document Number:

689302103**FIELD INSPECTION FORM**Loc ID 334875 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerus oilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211494	WELL	PR	08/30/2000	GW	045-07254	BENNETT 33-5	PR
258018	WELL	PR	06/01/2002	GW	045-07612	SHIDELER 32-8 (E33)	PR
258024	WELL	PR	06/01/2002	GW	045-07616	SHIDELER 32-9 (E 33)	PR
258068	WELL	PR	04/01/2017	GW	045-07617	SHIDELER 33-4 (E33)	PR

General Comment:[Routine Field Inspection](#)

Location					
Lease Road:					
Type	Access				
comment:					
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:	1-800-791-7691				
Corrective Action:					Date:
Good Housekeeping:					
Type	UNUSED EQUIPMENT				
Comment:	1 Joint of tubing on the East side of the wellheads, see photos				
Corrective Action:	Comply with Rule 603.f .				Date: 11/11/2018
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	SEPARATOR				
Comment:	Panel gates				
Corrective Action:					Date:
Type	WELLHEAD				
Comment:	Panel gates				
Corrective Action:					Date:
Type	TANK BATTERY				
Comment:	Hog panel fence				
Corrective Action:					Date:
Equipment:					
					corrective date
Type: Plunger Lift	# 4				
Comment:					
Corrective Action:					Date:
Type: Bird Protectors	# 4				
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 4				
Comment:					
Corrective Action:					Date:

Type: Deadman # & Marked	# 5	
Comment:	4 of 5 marked, deadman between tank battery and separators not marked, see photo	
Corrective Action:	Mark as required	Date: 10/26/2018

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	211494	Type:	WELL	API Number:	045-07254	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	258018	Type:	WELL	API Number:	045-07612	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	258024	Type:	WELL	API Number:	045-07616	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	258068	Type:	WELL	API Number:	045-07617	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding						
		Compaction				
Berms						
Ditches						
		Gravel				

Comment: [Hole in berm behind south corner of separators, water is draining into this hole and into ranchers field. see photo](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 10/26/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401793400	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4605977
689302104	Inspection photo 689302104	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4605971