

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/10/2018

Submitted Date:

10/10/2018

Document Number:

689701889**FIELD INSPECTION FORM**Loc ID 322458 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210549	WELL	SI	09/01/2017	GW	045-06305	COWPERTHWAIT 2-6 LW	SI

General Comment:

Routine General Field Inspection

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Label on chemical drum is damaged.		
Corrective Action:	Install sign to comply with Rule 210.d. Install sign to comply with Rule 210.e.	Date:	12/12/2018
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Batthey sign at separator. Sign does not meet Rule 210.b. No contact number or emergency contact (911) on sign. Nearest road to access location not on battery sign. Sign is rusting and previous operator info is still partialy visable.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	12/12/2018

Emergency Contact Number:

Comment: 970-285-2615 on Tank Label
970-301-1319 on Tank Label

Corrective Action:

Date:

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds and weed debris around well and staris to tank battery.		
Corrective Action:	Comply with Rule 603.f .	Date:	10/20/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	LOCATION		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		

Comment:		
Corrective Action:		Date:

Equipment:		corrective date
Type: Ancillary equipment	# 1	
Comment:	Drum chemical container at well.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	210549	Type:	WELL	API Number:	045-06305	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED									
Comment: <input type="text" value="SI Last production record Dec. 2016."/>									
Corrective Action: <input type="text"/> Date: <input type="text"/>									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
				Material Handling And Spill Prevention	Fail	Fluids in secondary containment.
Gravel	Pass					
		Culverts	Pass			
		Gravel	Pass			
		Compaction	Pass			

Comment: [Secondary containment for chemical drum has fluids in it.](#)Corrective Action: [Remove and dispose of fluids in secondary containment.](#)

Date: 10/12/2018

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401791948	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4604567
689701890	Inspection 689701889 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4604561