

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2018

Submitted Date:

10/18/2018

Document Number:

689801755**FIELD INSPECTION FORM**
 Loc ID 312973 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pape, Terry	970-768-5700	tpape@hrmres.com	<a href="#">All Inspections</a>
Payne, Gina		gpayne@hrmres.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223107	WELL	PR	03/16/2006	GW	081-06469	MOFFAT COUNTY 2	PR

**General Comment:**

Inspector was driving on Moffat County Road 7 and noticed a vapor release occurring on the location. Inspector drove to location and confirmed release was on location and called operator at 11:50 AM. Pumper arrived on location at 1:15 PM and shut-down equipment. Inspector was informed that the dehydrator pump had a high temp and lost pressure, causing an excess release of water vapor. No hydrocarbon release was observed and inspector left pumper on location repairing equipment.

**Inspected Facilities**Facility ID: 223107 Type: WELL API Number: 081-06469 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

Inspector was driving on Moffat County Road 7 and noticed a vapor release occurring on the location. Inspector drove to location and confirmed release was on location and called operator at 11:50 AM. Pumper arrived on location at 1:15 PM and shut-down equipment. Inspector was informed that the dehydrator pump had a high temp and lost pressure, causing an excess release of water vapor. No hydrocarbon release was observed and inspector left pumper on location repairing equipment.

User

waldrone

Date

10/18/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689801765	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614747">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614747</a>