

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2018

Submitted Date:

10/18/2018

Document Number:

688302625**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 317321      Sherman, Susan      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 24500Name of Operator: PADCO LLCAddress: P O BOX 5275City: BEVERLY HILLS      State: CA      Zip: 90209-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Crumley, Tim	(970) 768-5658	tcrumley@comcast.net	Pumper
Richmond, Dan	(918) 630-9912	dan@dsrinc.net	Field Operations Manager

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238073	WELL	SI	07/01/2018	OW	121-10576	SHARP 3	PA

**General Comment:**

PA Inspection

**Inspected Facilities**Facility ID: 238073 Type: WELL API Number: 121-10576 Status: SI Insp. Status: PA**Cement**Cement ContractorContractor Name: Yetter

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 4720'

Cement Volume (sx): \_\_\_\_\_ w

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment:

10/9/2018  
CIBP set by BrandX wireline with 2 sxs cement on top.  
10/11/2018  
Casing cut @ 2925' per pumper.  
10/12/2018  
Pumped stub plug and surface plug  
10/13/2018  
Per pumper, surface fell to 45', pumped more cement to surface  
10/17/2018  
Wellhead cut, capped and covered.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Workover**Comment:Yetter Rig #7/Chris

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: equipment removed (pumping unit)

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688302626	PADCO Sharp 3 wellsign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614873">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614873</a>
688302627	PADCO Shart 3 wireline	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614874">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614874</a>
688302733	PADCO Sharp 3 casing shot off	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614875">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614875</a>
688302734	PADCO Sharp 3 casing pulled	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614876">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614876</a>
688302736	PADCO Sharp 3 wellhead cut	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614877">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614877</a>
688302737	PADCO Sharp 3 wellhead cap	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614878">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614878</a>
688302738	PADCO Sharp 3 wellhead covered	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614879">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4614879</a>