

Inspection Photos
Location Name: Walker Ann #2
Location ID: 320177



Photo 1 PU



Photo 2 TNK BTRY

Inspection Photos
Location Name: Walker Ann #2
Location ID: 320177



Photo 3 Stained soil exhaust



Photo 4 Stained soil crude oil load out line

Inspection Photos
Location Name: Walker Ann #2
Location ID: 320177



Photo 5 Stained soil by meter run. Meter run locked out tagged out