

## Inspection Photos

Location Name: 05-045-09361 (FIGURE FOUR 8009B I25 498)

Location ID: 324242

Inspection: 679701195



**Location**



**Tear in tank liner**