

Inspection Photos

Location Name: Gunderson 0993-21-05

Location ID: #452797

Inspection Date: October 18, 2018



Photo #1 – Facility sign with location ID.



Photo #2 – View of cuttings pile (red arrow) from the south. Note absence of secondary containment berms and stormwater BMPs to isolate sediment and stormwater runoff from cuttings or to prevent tracking of material throughout pad.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Gunderson 0993-21-05
Location ID: #452797
Inspection Date: October 18, 2018



Photo #3 – View of cuttings pile (dark material) from NE corner of pad. Note storage of chemicals and equipment at NE corner of pad identical to Photo #9 included in 10/16/2018 Field Inspection Report (doc #692400233) photo log.



Photo #4 – Stormwater drain located at NE corner of pad. Note that there were no stormwater BMPs or secondary containment devices in place to prevent commingling of fluids from cuttings management pile with this area of the pad.

Inspection Photos

Location Name: Gunderson 0993-21-05

Location ID: #452797

Inspection Date: October 18, 2018



Photo #5 – Outlet of stormwater drain from previous photo (red arrow) and silt fence located north of pad.



Photo #6 - Collapsed section of pad containment berm and fill slope located on north side of pad.