

# Inspection Photos

Operator: BP Production

API: 05-067-07867

Date: 10/05/2018



**Photo 1. View of the project area from the southwestern corner facing center.**



**Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is progressing with shrubs such as rubber rabbitbrush (*Chrysothamnus nauseosus*), fringed sage (*Artemisia frigida*), and grasses such as sand dropseed (*Sporobolus cryptandrus*).**



**Photo 3. View of the western project area from the southwestern corner facing northward.**