

**Inspection Photo
Miller 5-36
API # 045-09192
Inspection # 689302161**



Location Photo #1

Location Photo #2

**Inspection Photo
Miller 5-36
API # 045-09192
Inspection # 689302161**



Location Photo #3, battery sign missing information.