

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2018

Submitted Date:

10/23/2018

Document Number:

680403958

FIELD INSPECTION FORM

Loc ID 311867 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10453
Name of Operator: PARADOX UPSTREAM LLC
Address: 600 TRAVIS STREET SUITE 300
City: HOUSTON State: TX Zip: 77002

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Miller, Mandy	970-739-3786	mandym@paradoxresources.com	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288565	WELL	PR	04/01/2018	GW	113-06228	COCKLEBUR DRAW 4	PR

General Comment:

[Bradenhead test performed 10/22/2018.](#)

Location

Lease Road:			
	Type	Access	
	comment:		
	Corrective Action		Date:
	Type	Main	
	comment:		
	Corrective Action		Date:

Overall Good:

Signs/Marker:			
	Type	TANK LABELS/PLACARDS	
	Comment:		
	Corrective Action:		Date:
	Type	WELLHEAD	
	Comment:		
	Corrective Action:		Date:

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>	
Corrective Action:	<input style="width: 95%;" type="text"/>	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	WELLHEAD	
	Comment:	Panel fence around wellhead.	
	Corrective Action:		Date:

Equipment:			corrective date
Type: Dehydrator	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities

Facility ID: 288565 Type: WELL API Number: 113-06228 Status: PR Insp. Status: PR

BradenHead

Comment: Bradenhead test peromed 10/22/2018. Tbg pressure 202 psi, casing pressure 214, bradenhead pressure -5 psi. Bradenhead pressure down to 0 after 5 minutes. No change in tubing or casing pressure.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680403966	Inspection photos 10/22/2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4618876