

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2018

Submitted Date:

10/23/2018

Document Number:

689302167

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10541  
Name of Operator: DIVIDE CREEK GATHERING SYSTEM LLC  
Address: PO BOX 290058  
City: BOSTON State: MA Zip: 02129

**Findings:**

2 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspections, All		inspection@sginterests.com	<a href="#">All Inspections</a>

**General Comment:**

This is a noise reading for Complaint #200444574. 2 additional noise reading were done, 1 at MR. Wellers property near his cabin, the other was NE of his cabin approximatley 150 yds up hill.

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302168	Noise reading at house	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4618878">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4618878</a>
689302169	Noise reading at Pipeline.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4618879">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4618879</a>