

Inspection Photos
Location Name: Thomson Price #2
Location ID: 320156



Photo 1 WH no Sign



Phot 2 Stained soil around PU motor

Inspection Photos
Location Name: Thomson Price #2
Location ID: 320156



Photo 3 Stained soil PU exhaust



Phot 4 TNK BTRY

Inspection Photos
Location Name: Thomson Price #2
Location ID: 320156



Photo 5 Weeds around SEP



Phot 6 no berm around crude oil tank

Inspection Photos
Location Name: Thomson Price #2
Location ID: 320156



Photo 7 Stained soil around Pro water fiberglass tank



Phot 8 Stained soil around Pro water fiberglass tank

Inspection Photos
Location Name: Thomson Price #2
Location ID: 320156



Photo 9 Stained soil around Produced water steel tank



Phot 10 Stained soil under load out line to pro water tank

Inspection Photos
Location Name: Thomson Price #2
Location ID: 320156



Photo 11 Weeds on location

