

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/24/2018

Submitted Date:

10/24/2018

Document Number:

689302184**FIELD INSPECTION FORM**

Loc ID 324162 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260224	WELL	PR	06/30/2002	GW	045-07837	CLOUGH RMV 154-27	PR

**General Comment:**[Routine Field Inspection](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type WEEDS

Comment:

Corrective Action:

Date:

Type TRASH

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type WELLHEAD

Comment: [Hog panel fencing](#)

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: [Chemical unit at wellheads](#)

Corrective Action:

Date:

Type: Deadman # & Marked # 3

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 260224 Type: WELL API Number: 045-07837 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Well Producing on plunger lift](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Seeding						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302185	Inspection photo 689302185	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4620612">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4620612</a>