

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/24/2018

Submitted Date:

10/24/2018

Document Number:

689302186

FIELD INSPECTION FORM

Loc ID 335269 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211118	WELL	PR	02/01/2018	GW	045-06877	RULISON DEEP 1	PR
294540	WELL	PR	02/15/2008	GW	045-15515	WEBSTER HILL, LLC RWF 314-27	PR
294543	WELL	PR	07/21/2008	GW	045-15516	WEBSTER HILL, LLC RWF 514-27	PR

General Comment:

[Routine Field Inspection](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	WEEDS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Hog panel fencing		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panel fencing		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panel fencing		
Corrective Action:			Date:

Equipment:

Type			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 211118 Type: WELL API Number: 045-06877 Status: PR Insp. Status: PR

Producing Well

Comment: [Well Producing on plunger lift](#)

Corrective Action:

Date:

Facility ID: 294540 Type: WELL API Number: 045-15515 Status: PR Insp. Status: PR

Producing Well

Comment: [Well Producing on plunger lift](#)

Corrective Action:

Date:

Facility ID: 294543 Type: WELL API Number: 045-15516 Status: PR Insp. Status: PR

Producing Well

Comment: [Well Producing on plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						
		Compaction				
Gravel						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302187	Inspection photo 689302187	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4620613