

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/16/2018

Submitted Date:

10/25/2018

Document Number:

688800323**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Hughes, Jim 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 87830Name of Operator: THOMPSON ENGINEERING & PRODUCTIONAddress: 7415 E MAINCity: FARMINGTON State: NM Zip: 87402**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Thompson, John		john@walsheng.net	Consultant

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205067	WELL	PA	11/17/2005	GW	007-05180	PERINO 1	EI

General Comment:

On October 16, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Thompson Engineering and Production Co. Perino #1 Pit Facility ID #104970.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	PA marker for Perino #1 (API #007-05180).		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PITType: Lined: Pit ID: 104970 Lat: 37.015842 Long: -107.453905Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Operator shall submit a Form 27 with any available information regarding Pit Facility ID #104970 per Rule 905.Corrective Action: Date: 11/05/2018**COGCC Comments**

Comment	User	Date
On October 16, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Thompson Engineering and Production Co. Perino #1 Pit Facility ID #104970. For the most recent field inspection report of this location, please refer to document #200302455. No surface indication of a pit was observed during this field inspection. The operator shall submit a Form 27 per Rule 905 to close this pit in the COGIS database.	hughesjo	10/25/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800324	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4621288