

Inspection Photos

Operator: BP Production

API: 05-067-07843

Date: 10/05/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing within the interim reclamation areas with shrubs such as rabbitbrush (*Chrysothamnus nauseosus*), and grasses such as intermediate wheatgrass (*Thinopyron intermedium*).





Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of the southwestern portion of the project area. Erosional channels and deep rills are forming within the cut-slope. Exposed roots are visible.



Photo 5. View of erosional channels in the southwestern cut-slope, approximately 2 to 3 feet wide and deep.



Photo 6. View of diversion ditch from western and southwestern cut-slope, full of sediment and not properly stabilized.



Photo 7. View of cobble run-down in the southeastern project area that appears to be functioning.