

Inspection Photos

Operator: BP Production

API: 05-067-09700

Date: 10/05/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing within the interim reclamation areas with grasses such intermediate wheatgrass (*Thinopyron intermedium*) .



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of erosional channels up to 1 foot wide and deep forming within the southeastern project area.



Photo 5. View of erosional channels in the northeastern portion of the project area.



Photo 6. View of more erosional channels within the eastern project area.



Photo 7. View of the northern portion of the project area from the northeastern corner facing westward.