

Inspection Photos  
Location Name: Schumacher 32-6 #13-3  
API: 05-007-06239



Schumacher 32-6 #13-3 location sign. Label and placard on western tank are illegible.



Fluid observed in secondary containment berm. Reportedly storm water.

Inspection Photos  
Location Name: Schumacher 32-6 #13-3  
API: 05-007-06239



Well head is wet and stained.



Schumacher 32-6 #13-3 location photo.