

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2018

Submitted Date:

10/25/2018

Document Number:

688302816**FIELD INSPECTION FORM**Loc ID 453244 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: 600 N DAIRY ASHFORD RDCity: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:25 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ConocoPhillips		COPColoradoReg@conocophillips.com	
Aldrich, Brian	307-240-1882	Brian.C.aldrich@conocophillips.com	Production
Yu, Liang	281-467-5712	Liang.Yu@conocophillips.com	Regulatory Coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453716	WELL	PR	08/01/2018		005-07328	Cottonwood Creek 4-65 27-28 4AH	PR
453718	WELL	PR	08/01/2018		005-07329	Cottonwood Creek 4-65 27-28 4BH	PR
453719	WELL	PR	08/01/2018		005-07330	Cottonwood Creek 4-65 27-28 3DH	PR
453721	WELL	PR	08/01/2018	OW	005-07331	Cottonwood Creek 4-65 27-28 3CH	PR

General Comment:Routine Inspection
Multiwell pad

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	location sign at gate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 855-595-8258

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Diesel stained soil SW of wells. Contacted operator on 10/25/2018 and it will be cleaned up. Stained soil at tank battery truck load out area.		
Corrective Action:	Non E&P Waste not properly handled or disposed of per Rule 907A.	Date:	10/29/2018
Type	TRASH		
Comment:	Trash around tank battery location.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:	barbed wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 4		
Comment:	In Use: between well and separators marked with yellow and white poles.		

Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	GPS 39.668796, -104.644856		
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:	GPS 39.668399, -104.644678		
Corrective Action:		Date:	
Type: VRU	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	generator/2 propane tanks		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	GPS 39.668399, -104.644591, burning		
Corrective Action:		Date:	
Type: FWKO	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:	GPS 39.668642, -104.645330		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	STEEL AST		39.668763,-104.645015
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	750 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Sherman, Susan

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: enginnered liner					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	7	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity) 750 bbls					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: same metal berms as produced water tanks					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	453716	Type:	WELL	API Number:	005-07328	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR-flowing. Aug 2018 production reported to COGCC database. GPS 39 40.108, -104 38.755								
Corrective Action:						Date:			
BradenHead									
Comment:	1 psi Tubing 619 psi								
Corrective Action:						Date:			
Facility ID:	453718	Type:	WELL	API Number:	005-07329	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR-flowing. Aug 2018 production reported to COGCC database. GPS 39 40.133, -104 38.756								
Corrective Action:						Date:			
BradenHead									
Comment:	1 psi Tubing 711 psi								
Corrective Action:						Date:			
Facility ID:	453719	Type:	WELL	API Number:	005-07330	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR-flowing. Aug 2018 production reported to COGCC database. GPS 39 40.120, -104 38.755								
Corrective Action:						Date:			
BradenHead									
Comment:	0 psi Tubing 533 psi								
Corrective Action:						Date:			
Facility ID:	453721	Type:	WELL	API Number:	005-07331	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR-flowing. Aug 2018 production reported to COGCC database. GPS 39 40.126, -104 38.756								
Corrective Action:						Date:			
BradenHead									
Comment:	0 psi Tubing 545 psi								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts	Fail					
Check Dams	Fail					

Comment: Check dams at entrance, going down the hill are filled with sediment (see attached photo).
Erosion at culvert at bottom of entrance hill (see attached photo).

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 11/26/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688302829	ConocoPhillips Cottonwood Creek 4-65 27 -28	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4621903