

Inspection Photos
Location Name: Anderson 43-29
API: 05-081-07184



Photo 1. Overview of location taken at entrance facing southeast.



Photo 2. Previous operator emergency contact number on tank battery sign and labels.

Inspection Photos
Location Name: Anderson 43-29
API: 05-081-07184



Photo 3. No wellhead sign.



Photo 4. Barrel without secondary containment.

Inspection Photos
Location Name: Anderson 43-29
API: 05-081-07184



Photo 5. Equipment stored on location perimeter.



Photo 6. Equipment stored on location perimeter.

Inspection Photos
Location Name: Anderson 43-29
API: 05-081-07184



Photo 7. Equipment stored on location perimeter.



Photo 8. Equipment stored on location perimeter.

Inspection Photos
Location Name: Anderson 43-29
API: 05-081-07184



Photo 9. Equipment stored on location perimeter.



Photo 10. Equipment stored on location perimeter.

Inspection Photos
Location Name: Anderson 43-29
API: 05-081-07184



Photo 11. Equipment stored on location perimeter.



Photo 12. Equipment stored on location perimeter.