

# Inspection Photos

Operator: DJ Simmons Inc.

API: 05-033-06063

Date: 9/18/2018



**Photo 1. View of the project area from the southwestern corner facing center.**





**Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing within outer reclamation areas with grass such as crested wheatgrass (*Agropyron cristatum*) and shrubs such as rubber rabbitbrush (*Chrysothamnus nauseosus*).**





**Photo 3. View of the northern portion of the project area from the northwestern corner facing eastward.**