

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2018

Submitted Date:

10/26/2018

Document Number:

690100856**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ Maclaren, Joe _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 4680Name of Operator: DCP OPERATING COMPANY LPAddress: 370 17TH STREET - SUITE 2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Candice (Nikki)		candice.graber@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
JONES, JEANETTE		jajones@dcpmidstream.com	
Hayes, Branden	970-373-8905	bshayes@dcpmidstream.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458322	SPILL OR RELEASE	AC	10/26/2018		-	Knaub 9-13G Pipeline Release	EG

General Comment:

Engineering integrity inspection performed on October 24th, 2018 in response to initial form 19 spill report Doc #401806989 received by COGCC on 10/18/2018 that outlines: DCP Environmental was informed by DCP Pipeline group of a possible pipeline release on October 22nd, 2018 around 2:00 pm. At the time of notification the DCP pipeline group had identified that a 2 inch gas gathering pipeline might have developed a leak. There was no visible staining on the surface to indicate soil contamination; however, while excavating the pipeline to perform a disconnect, operations discovered the soil was stained and had a strong odor. The pipeline has been isolated and blowdown, and until repairs have been made the pipeline will remain out of service. Details of observations made during this field inspection are available in the comment section of this report. Photos uploaded.

Inspected Facilities

Facility ID: 458322 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
Excavation activities observed around the Noble Energy Knaub #9-13G (API 123-15767) gas meter run and tank battery. This well is currently shut in, flowlines locked and tagged out. No DCP or contract personnel were on site at the time of this field inspection. Initial spill response and cleanup efforts have been performed; It is unclear if repairs have been completed on the 2" gas gathering pipeline.	maclarej	10/26/2018
Note: Document findings of the root cause of failure and a description of pipeline repairs completed in the corrective actions section of COGCC supplemental form 19; Confirm integrity of repairs completed prior to returning gas lines to service.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100859	Tank battery and signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4622950
690100860	Production equipment and gas meter run	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4622951
690100861	Excavation at discharge of gas meter run	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4622952