

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/10/2018

Submitted Date:

10/10/2018

Document Number:

689302092

**FIELD INSPECTION FORM**

Loc ID 334069 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	Pipeline group
Pesicka, Conor		conor.pesicka@state.co.us	
Elsener,		COGCC.inspections@caerusoilandgas.com	all Piceance inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262866	WELL	PR	09/17/2002	GW	045-08064	SHIDLER 1-7 (G1)	PR
268506	WELL	PR	07/08/2004	GW	045-09268	HMU 1-6D (G1)	PR
282079	WELL	PR	08/25/2006	GW	045-11633	SHIDLER FEDERAL 1-9 (G1SW)	PR
282080	WELL	PR	08/26/2006	GW	045-11632	SHIDLER FEDERAL 1-2C (G1SW)	PR
282081	WELL	PR	07/21/2006	GW	045-11631	SHIDLER 1-1C (G1SW)	PR

**General Comment:**

[Routine Filed Inspection](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Emergency Contact Number:			
Comment:	1-800-791-7691		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	2 unused flowline risers behind separators		
Corrective Action:	comply with rule 603. f. For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		Date: 11/10/2018
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	panel fence		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Plunger Lift	# 5		corrective date
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			

Corrective Action:	Date:
--------------------	-------

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		

Comment: centralized battery

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	Adequate	
Other (Content)	Methanol tank	
Other (Capacity)	1000 gallon	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:

Corrective Action:	Date:
--------------------	-------

**Venting:**

Yes/No	NO	Date:	Date:
--------	----	-------	-------

Comment:

Corrective Action:	Date:
--------------------	-------

**Flaring:**

Type		Date:
------	--	-------

Comment:

Corrective Action:	Date:
--------------------	-------

Inspected Facilities									
Facility ID:	<u>262866</u>	Type:	<u>WELL</u>	API Number:	<u>045-08064</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>268506</u>	Type:	<u>WELL</u>	API Number:	<u>045-09268</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>282079</u>	Type:	<u>WELL</u>	API Number:	<u>045-11633</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>282080</u>	Type:	<u>WELL</u>	API Number:	<u>045-11632</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>282081</u>	Type:	<u>WELL</u>	API Number:	<u>045-11631</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds						
Berms						
		Compaction				
		Gravel				
Ditches						
Seeding						
Culverts						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401791857	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4604430">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4604430</a>
689302093	Inspection photo 689302093	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4604424">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4604424</a>