

Inspection Photos

Operator: BP Production

API: 05-067-08778

Date: 10/16/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing within the interim reclamation areas with grasses such as sand dropseed (*Sporobolus airoides*) and intermediate wheatgrass (*Thinopyron intermedium*).



10.16.2018

Photo 3. View of the southwestern project area from the southwestern corner facing northward.



Photo 4. View of cobble rundown in the southwestern corner that appears to be functioning.



Photo 5. View of Russian knapweeds (*Acroptilon repens*) within the southeastern project area. Approximately 30 individuals observed.