

Construction and Stormwater Inspection

October 25, 2018

Operator: MALLARD EXPLORATION LLC- #10670

Location ID: 456368

Inspection Document #: 682404096

Weld County, CO

SWSE Section 24 T8N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Khaki Campbell East /Pad
Location ID: 456368



Photo 1. Photo taken from the entrance of location off Highway 14, facing South. Operator has installed a culvert along the roadside ditch and gravel at the entrance.



Photo 2. Photo taken from the entrance of the location, facing East. Operator has installed vehicle tracking devices which appear to be in proper functioning condition.

Inspection Photos
Location Name: Khaki Campbell East /Pad
Location ID: 456368



Photo 3. Photo taken from the eastern perimeter of the location, facing North. Operator has installed 2 sets of ditch and berm BMPs around the location.



Photo 4. Photo taken from the northeastern perimeter of the location, facing North. Photo illustrates the topsoil stockpile which has been temporarily stabilized with equipment tracking.

Inspection Photos
Location Name: Khaki Campbell East /Pad
Location ID: 456368



Photo 5. Photo taken from the northeast perimeter of the location, facing West. Operator has installed a sediment trap with a stabilized outlet.



Photo 6. Photo taken from the northwestern perimeter of the location, facing South. See comments under Photo 3.

Inspection Photos
Location Name: Khaki Campbell East /Pad
Location ID: 456368



Photo 7. Photo taken from the northwestern perimeter of the location, facing East. Photo illustrates the northern well pad area which has been compacted but not necessarily stabilized from wind erosion. Operator shall ensure compliance with Rule 1002.e.(1) to reasonably control dust and minimize erosion which includes wind erosion.

Inspection Photos
Location Name: Khaki Campbell East /Pad
Location ID: 456368



Photo 8. Photo taken from the western perimeter of the location, facing East. Photo illustrates the southern well pad area which has been compacted but not necessarily stabilized from wind erosion. See comments under Photo 7.

Inspection Photos
Location Name: Khaki Campbell East /Pad
Location ID: 456368



Photo 9. Photo taken from the southwestern perimeter of the location, facing East. See comments under Photo 3.



Photo 10. Photo taken from the southeastern perimeter of the location, facing North. See comments under Photo 3.