

Inspection Photos

Operator: BP Production

API: 05-067-06629

Date: 10/16/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Vegetation is progressing with grasses such as sand dropseed (*Sporobolus airoides*) and western wheatgrass (*Pascopyrum smithii*).



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of the Russian knapweeds (*Acroptilon repens*) within the southern project area. Approximately 1500 individuals observed.



Photo 5. View of cobble run-down within the southern project area. Appears to be installed after formation of erosional channel. This needs to be monitored.