

Inspection Photos

Operator: BP Production

API: 05-067-06610

Date: 10/16/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Vegetation is progressing with shrubs such as rubber rabbitbrush (*Chrysothamnus nauseosus*).





Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of the southern project area from the southwestern corner facing eastward. Kochia debris, up to three feet tall, needs to be removed.



Photo 5. View of musk thistles (*Carduus nutans*) within the northern project area.



Photo 6. View of cobble run-down in the southwestern project area, appears to be functioning.