

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/29/2018

Submitted Date:

10/29/2018

Document Number:

689302216

FIELD INSPECTION FORM

Loc ID 324012 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211489	WELL	PR	09/01/2004	GW	045-07249	GIBSON GULCH UNIT 9-30	PR

General Comment:

[Routione Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Emergency Contact Number:			
Comment:	1-800-921-8252		
Corrective Action:			Date:

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	UNUSED EQUIPMENT		
Comment:	unused pipe beind tank battery, see photo		
Corrective Action:	Comply with 603. f.		Date: 11/29/2018
Type	WEEDS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Panel gates		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Panel gates		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Panel gates		
Corrective Action:			Date:

Equipment:			corrective date
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLs	STEEL AST			
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	YES	
Comment:	Braden heads open to vent.	
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 211489 Type: WELL API Number: 045-07249 Status: PR Insp. Status: PR

Producing Well

Comment: [Well Producing on plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Gravel				
Berms						
		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302217	Inspection photo 689302217	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4624745