

Inspection Photos

Operator: BP Production

API: 05-067-06611

Date: 10/16/2018



Photo 1. View of the project area from the northeastern corner facing center. Well pad is recently countoured. It appears topsoil is being spread.



Photo 2. View of the northern project area from the northeastern corner facing westward.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of southern project area from the southeastern corner facing westward. Recontouring and other reclamation is in process.



Photo 5. View of reference vegetation south of the project area.