

Reclamation and Stormwater Inspection

October 25, 2018

Operator: CONFLUENCE DJ LLC- #10518

Location ID: 457632

Inspection Document #: 682404118

Weld County, CO

NESE Section 7 T7N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Pickaroon South
Location ID: 457632



Photo 1. Photo taken from the entrance of the location, facing West. Tracking pad devices installed at the entrance off County Road 51 appears to be in proper functioning condition.



Photo 2. Photo taken from the western location, facing North. Photo illustrates a retention area installed in conjunction with a ditch and berm BMP. Appears portions of the berm have been tracked with equipment for temporary stabilization but portions have been left unconsolidated.

Inspection Photos
Location Name: Pickaroon South
Location ID: 457632



Photo 3. Photo taken from the southwest location, facing West. Photo illustrates a retention area with a stabilized outlet.



Photo 4. Photo taken from the southern location, facing North. Photo illustrates a temporarily stabilized outlet along the fill slope that is directed to the ditch and berm BMP. Fill slopes have been temporarily stabilized with equipment tracking.

Inspection Photos
Location Name: Pickaroon South
Location ID: 457632



Photo 5. Photo taken from the southern location, facing East. A total of three temporary outlets have been installed along the southern fill slope. See comments under Photo 4. Photo illustrates the ditch and berm BMP. Does not appear portions of the berm have been sufficient stabilized.



Photo 6. Photo taken from the southeastern location, facing West. Photo illustrates equipment that has damaged the ditch and berm BMP. Operator shall ensure stormwater BMPs are in proper functioning condition.

Inspection Photos
Location Name: Pickaroon South
Location ID: 457632



Photo 7. Photo taken from the eastern location, facing North. See comments under Photo 2.



Photo 8. Photo taken from the entrance of the location, facing North. Photo illustrates a culvert installed in conjunction with the ditch and berm BMP. Also, photo illustrates the vehicle tracking devices.

Inspection Photos
Location Name: Pickaroon South
Location ID: 457632



Photo 9. Photo taken from the northeastern location, facing West. Photo illustrates the topsoil stockpile that has been temporarily stabilized with equipment tracking.



Photo 10. Photo taken from the northwestern location, facing South. See comments under Photo 5.

Inspection Photos
Location Name: Pickaroon South
Location ID: 457632



Photo 11. Photo taken from the northwestern location, facing Southeast. Photo illustrates the northern well pad area which has been compacted but not necessarily stabilized from wind erosion. Operator shall ensure compliance with Rule 1002.e.(1) to reasonably control dust and minimize erosion which includes wind erosion.

Inspection Photos
Location Name: Pickaroon South
Location ID: 457632



Photo 12. Photo taken from the western location, facing East. See comments under Photo 11.