

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/31/2018

Submitted Date:

10/31/2018

Document Number:

679701577

FIELD INSPECTION FORM

Loc ID 316409 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, Foundation		regulatory@foundationenergy.com	Regulatory
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	
Waldron, Emily		emily.waldron@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272888	WELL	SI	05/01/2016	GW	103-10455	COLUMBINE SP FED 9C-15-4-104	TA

General Comment:

[Follow up inspection to document 6751013184](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers. No signage on tank.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	12/28/2018

Emergency Contact Number:			
Comment:	866-767-3600		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:				corrective date
Type: Deadman # & Marked	# 2			
Comment:				
Corrective Action:		Date:		
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:		Date:		
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:		Date:		
Type: Pig Station	# 1			
Comment:				
Corrective Action:		Date:		
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:		Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	PBV FIBERGLASS		39.712300,-109.050400
Comment:	<input type="text"/>				

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 272888 Type: WELL API Number: 103-10455 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Last recorded production October 2013. Notice of intent for an MIT submitted 28 October 2015. No record of an MIT that was done is on file.

Corrective Action: Well must have a successful mechanical integrity test performed or plugged as directed by Rule 319 b (3)

Date: 12/14/2016

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679701578	inspection 679701577 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4628429