

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/15/2018

Submitted Date:

10/15/2018

Document Number:

689302122**FIELD INSPECTION FORM**

Loc ID 335376 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	Pipeline group
Elsener,		COGCC.inspections@caerus oilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261293	WELL	PR	07/17/2002	GW	045-07941	GMR 27-2B1 (B27)	PR
261294	WELL	PR	05/13/2014	GW	045-07942	GMR 27-3D1 (B27)	PR
261296	WELL	PR	09/18/2002	GW	045-07944	GMR 27-7B1 (B27)	PR
263861	WELL	PR	10/27/2002	GW	045-08148	GMR 22-15D (B27)	PR

General Comment:

Routine Field Inspection

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:	1-800-791-7691			
Corrective Action:			Date:	
Good Housekeeping:				
Type	OTHER			
Comment:	Stained material in battery containment.			
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e..		Date:	11/15/2018
Type	UNUSED EQUIPMENT			
Comment:	Unused flow line risers			
Corrective Action:	Comply with rule 603.f. For unused, unmarked flowline risers, 24 hrs to LOTO, 30 days to remove riser		Date:	11/15/2018
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	4 strand barbed wire			
Corrective Action:			Date:	
Equipment:				
Type: Horizontal Separator	# 1			corrective date
Comment:				
Corrective Action:			Date:	
Type: Deadman # & Marked	# 5			
Comment:	4 of 5 marked, 1 anchor on East end of location not marked			
Corrective Action:	Mark as required		Date:	10/30/2018
Type: Pig Station	# 4			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:				

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Blow down vessel on East end of location.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)	Methanol tank	
Other (Capacity)	1000 gallon	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	261293	Type:	WELL	API Number:	045-07941	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	261294	Type:	WELL	API Number:	045-07942	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	261296	Type:	WELL	API Number:	045-07944	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	263861	Type:	WELL	API Number:	045-08148	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Gravel				
Ditches						
Slope Roughening						
		Compaction				
Seeding						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401797212	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4609769
689302123	Inspection photo 689302123	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4609762